

---

---

**R001.0 Rev. A:**    *WORKMANSHIP*

**Deliverables Required:** None

**Frequency:** -

**Location:** -

The Product Shall Be Uniform in Quality, Condition, and Free From Foreign Objects and Debris (FOD). There Shall be no Imperfections Detrimental to the Usage of the Product.

- Parts Shall be Fabricated in a Thorough Manner and All Manufacturing, Processing, and Assembly Operations Shall be Correctly Performed.
- Parts Shall be Clean and Free of Burrs, Sharp Edges, Voids, Seams, Cracks, Pores, Warping, Distortion, Chips, Surface Defects, Dirt, Grease, Oil, Rust / Corrosion, and Other Foreign Matter.
- Required Markings Shall be Sharply Defined and Legible.